

THE RIGHT WAY



Right height for the job -
no overreaching

Good grip

Correct flat shoes


Clean rungs

Ladder in good condition

Firm and level base

Ladder at correct angle -
75 degrees

Wider at the base



THE WRONG WAY

Electrical hazard

Overhead hazard

Wrong height for the job - overreaching

Not holding on - only 2 points of contact

Overloaded with materials

Standing beyond the last marked rungs

Incorrect footwear

Mud on rungs

Damaged ladder

Foot missing or damaged

Unstable surface

Ladder not wider at base

Base too far from wall

